

Pittsboro A.D.A Assessment

Report Summary – August 17, 2015

Site: **Summary:** Town Manager's Office The single most significant accessibility issue is the restroom. It is entirely non-compliant. Other issues exist, but this is the most significant. See attached report. Town Hall The public portion of the Town Hall has a few A.D.A. compliance issue, but is largely accessible. The public restrooms will need to be addressed. In contrast, the employee portion of the facility has many compliance issues. See attached report. Wastewater Building The wastewater facility is largely compliant. Its most significant issue is accessible parking and access into the building. See attached report. Water Plant The water plant is no longer in use by the town. The property is only maintained. No assessment of the facility was made. Park Office The park office is small former residence that is entirely non-compliant. Significant work is required to achieve genuine accessibility. The cost of such work is likely prohibitive. Scott Park This sports park is comprised of a baseball diamond with associated concessions, restroom, maintenance building and playground. It is largely non-compliant but has the space to accommodate accessibility upgrades. See attached report. Scamahorn Park This large community park is comprised of 4 buildings, playground, walking trail and a network of drives with

attached report.

parking lots. It is largely non-compliant. Significant work is required to achieve genuine accessibility. See